

SGS New Zealand Ltd, NDT & Materials Services P O Box 12-356, Penrose, Auckland, New Zealand 22 Vestey Drive, Mt Wellington, Auckland, New Zealand Tel: (64-9) 634 3637 Fax: (64-9) 634 6728

Amended Report

This replaces previous Report no.: INZ61052-01 dated 23/11/17.

Page 1 of 2

File Ref: INZ 61052

TEST REPORT No.: INZ61052-01A

Client: Set Engineering

Order No.: TBA

Sample Description:

Identification:

Material Specification:

Tested in accordance with:

JG2 steel bracket

As listed below

Unspecified steel

Client instruction

Test: Tensile testing of JG2 steel bracket fixed to 90mm x 45mm timber with 14g x 35mm

type 17 wood screws (Figure 1).

Method: With the base retained, apply a tensile load to the bracket assembly by applying a load

to the extending timber with the use of two steel angles fixed with two M10 class 8.8

bolts (Figure 2). Measure and record the ultimate load.

Loading Rate - 0.5 kN/s

Results:

Sample	Ultimate Load (kN)	Mean	Standard deviation	Characteristic Strength (kN)
1	22.0			
2	25.0			
3	22.2			
4	21.3			
5	25.7			
6	22.3	23.2	1.9	18.6
7	21.7			
8	20.5			
9	26.0			
10	25.7			
11	22.5			




Figure 1 - JG2 bracket assembly as supplied



SGS New Zealand Ltd, NDT & Materials Services P O Box 12-356, Penrose, Auckland, New Zealand 22 Vestey Drive, Mt Wellington, Auckland, New Zealand Tel: (64-9) 634 3637 Fax: (64-9) 634 6728

File Ref: INZ 61052

Page 2 of 2

TEST REPORT No.: INZ61052-01A




Figure 2 - Tensile test setup



Figure 3 - Typical failure, screws pulling out of timber base.

Acceptance Criteria:

Report findings

Tested by:

G. Schoutens

Checked by:

N. Woods



Date:

23-Nov-17

Date:

19-Dec-17

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at www.sgs.com/terms_and_conditions.htm and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at www.sgs.com/terms_e-document.htm. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law.

Unless otherwise stated the results shown in this test report refer only to the sample(s) tested and such sample(s) are retained for 14 days only.